

TECHNICAL ASSESSMENTS (5 EXAMPLES AMONGST OTHERS)

WARSAW AIRPORT, WARSAW, POLAND

2012 Assessment condition existing hydrant

LONDON CITY AIRPORT, LONDON, UNITED KINGDOM

2014 Assessment condition existing fuel facility – concept design extension existing fuel facility

OILTANKING, HONAU, GERMANY

2014 JIG 3 assessment of existing receipt, storage and distribution infrastructures to be made compliant for Jet A1

OILTANKING, ANTWERP, BELGIUM

2016 EI 1530 assessment of existing receipt, storage and distribution infrastructures to be made compliant for Jet A1

ULAANBAATAR INT'L AIRPORT, MONGOLIA

2017 Assessment design of hydrant under construction and recommendations for cost effective solutions to align hydrant with international aviation codes and standards